



Production plants- risk assessment

Rotoplas Group

Index

1. Quantitative physical risk assessment	3
2. Qualitative physical risk assessment	9
3. Appendix- Example of quantitative risk assessment	13

1. Quantitative assessments

NatCat Assessment, Swiss Re

In this document we present quantitative studies carried out to 10 of our production plants, in order to determine physical risks caused by Climate Change.

In the next slide a summary table is presented where all of the risks assessed in the NatCat Assessment, Swiss Re, are summarized.

The following slides show the graphs generated for each of the sites assessed.

In the appendix section, the complete overview of the assessments is presented.

Quantitative risk assessments


NatCat Assessment, Swiss Re

Production plant	River Flood	Pluvial flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Anáhuac	Moderate		Low	High	Low	Moderate	Moderate	Low	Moderate	Low	High
Mty Compuestos	Low		Low	Low	Low	Low	Low	Low	Moderate	Low	High
Mty Rotomoldeo	Low		Low	Low	Low	Low	Low	Low	Moderate	Low	High
Pacífico	Low	Low	Low	High	Low	High	Low	Low	High	Low	High
Golfo	Low	Low	Low	Moderate	Low	Moderate	Low	Low	Moderate	Low	High
Guadalajara	Low	Low	Low	Moderate	Low	Moderate	Low	Low	High	Low	High
León Rotopinsa	Low		Low	Low	Low	Moderate	Low	Low	Moderate	Low	Moderate
León Rotomoldeo	Low		Low	Low	Low	Moderate	Low	Low	Moderate	Low	Moderate
Mérida	Low	Low	Low	Low	Low	High	Low	Low	High	Low	High
Perú	High	Moderate	Low	High	Low	Low	Low	Low	Moderate	Low	Low

NatCat Risk Assessment Report

Hazard Overview

Global intensity per peril according to Swiss Rescale 1 = 10 (0: no data)




Peril Legend

River Flood	Tsunami	Tornado	Volcano
Return Period [years]	Return Period	Return Period [Year]	Ash Thickness [cm]
50	≤ 50 years	Very High (> 0.75)	Extreme (> 100 cm)
100	50-100 years	High (0.6 - 0.75)	Very High (50 - 100 cm)
200	250-200 years	Significant (0.35 - 0.5)	Very High (40 - 50 cm)
500	500-1000 years	Moderate (0.2 - 0.35)	High (30 - 40 cm)
1000	1000 years	Low (1.1 - 0.2)	High (20 - 30 cm)
2000	Windstr...	Very Low (< 0.1)	Significant (10 - 20 cm)
5000	Windstr...	No Observation	Moderate (5 - 10 cm)
10000	60 Year Peak Gust Range [m/s]		Low (2 - 5 cm)
40000	Extreme (≥ 70 m/s)		Low (1 - 2 cm)
100000	Very High (60-70 m/s)		Low (0.1 - 1 cm)
200000	High (50-60 m/s)		
500000	Mod. (40-50 m/s)		
1000000	Low (20-25 m/s)		
2000000	Mod. (10-15 m/s)		
5000000	Low (5-10 m/s)		
10000000	Mod. (2-5 m/s)		
20000000	Low (1-2 m/s)		
50000000	Mod. (0.5-1 m/s)		
100000000	Low (0.1-0.5 m/s)		
200000000	Mod. (0.05-0.1 m/s)		
500000000	Low (0.01-0.05 m/s)		
1000000000	Very Low (< 0.01 m/s)		

NatCat Risk Assessment Report

Hazard Overview

Global intensity per peril according to Swiss Rescale 1 = 10 (0: no data)



Peril Legend


River Flood	Tsunami	Tornado	Volcano
Return Period [years]	Return Period	EF-P/Tornadoes/Year	Ash Thickness [cm]
50	≤ 50 years	Very High (> 0.75)	Extreme (> 100 cm)
100	50-100 years	High (0.6 - 0.75)	Very High (60 - 100 cm)
200	250 years	Significant (0.35 - 0.5)	Very High (40 - 60 cm)
500	500 years	Moderate (0.2 - 0.35)	High (30 - 40 cm)
1000	1000 years	Low (1.1 - 0.2)	High (20 - 30 cm)
2000	Windstr...	Very Low (< 0.1)	Significant (10 - 20 cm)
5000	Windstr...	No Observation	Moderate (5 - 10 cm)
10000	Windstr...		Low (2 - 5 cm)
20000	Windstr...		Low (1 - 2 cm)
50000	Windstr...		Low (0.1 - 1 cm)
100000	50 Year Peak Gust Range [m/s]		
200000	Extreme (> 70 m/s)		
500000	Very High (60-70 m/s)		
1000000	High (50-60 m/s)		
2000000	Mod. (40-50 m/s)		
5000000	Low (20-25 m/s)		
10000000	Mod. (10-15 m/s)		
20000000	Low (5-10 m/s)		
50000000	Mod. (2-5 m/s)		
100000000	Low (1-2 m/s)		
200000000	Mod. (0.5-1 m/s)		
500000000	Low (0.1-0.5 m/s)		
1000000000	Very Low (< 0.01 m/s)		

Rotoplas 2020
Planta Monterrey

NatCat Risk Assessment Report

Hazard Overview

Global literacy per pair according to Swiss Re scale 1 - 10 (C: no data)




Peril Legend

River Hazard	Tsunami	Tornado	Volcanoes
Return Period [years]	Return Period	F2-F5 Tornadoes/Year	Volcanic Threatness (cm)
50	500 years	Very High (> 0.75)	Extreme (> 100 cm)
100	1000 years	High (0.5 - 0.75)	Very High (40 - 100 cm)
200	2400 years	Significant (0.38 - 0.5)	Very High (40 - 60 cm)
500	6400 years	Moderate (0.2 - 0.35)	High (20 - 40 cm)
Storm Surge	10000 years	Low (0.1 - 0.3)	High (10 - 20 cm)
Return Period [years]	Windstorms	Very Low (< 0.1)	Significant (10 - 20 cm)
50 years	50 Year Peak Gust Range (m/s)	No Observation	Moderate (5 - 10 cm)
100 years	Extreme (> 20 m/s)	Wildfires	Low (2 - 5 cm)
250 years	Very High (60-20 m/s)	Fire Hazard per 0.25° grid (1995-2014)	Low (1 - 2 cm)
500 years	High (60 m/s)	Extreme (1.0)	Lightning
1000 years	Significant (40-50 m/s)	Very High (0.5)	Annual flash rate per km ²
Sediment Hazard	Moderate (35-40 m/s)	High (0.3)	Extreme (> 50)
Pseudo Seismic Acceleration (g)	Low (20-30 m/s)	Significant (0.7)	Very High (26-50)
Extreme (1.82-2.0)	Low (20-29 m/s)	Moderate (0.5)	Very High (20-35)
Very High (1.31-1.82)	Very Low (<20 m/s)	Low (0.4)	High (2-12)
Very High (0.91-1.22)	Hailstorms	Low (0.3)	High (16-20)
High (0.61-0.82)	Hail day (~20n) per 2500 km ²	Very Low (0.2)	Significant (11-15)
High (0.41-0.61)	and year	Very Low (0.1)	Significant (7-10)
Significant (0.27-0.41)	Extreme (1.0)	Very Low (0.0)	Moderate (4-6)
Moderate (0.18-0.27)	Very High (0.8 - 1.0)		Low (1-3)
Low (0.14-0.18)	High (0.6 - 0.8)		Very Low (<1)
Low (0.09-0.14)	Significant (0.4 - 0.6)		
Very Low (0.06-0.09)	Moderate (0.2 - 0.4)		
	Low (0.1 - 0.2)		
	Very Low (0.0 - 0.1)		

NatCat Risk Assessment Report

Hazard Overview

Global intensity per peril according to Swiss Re scale 1 - 10 (0: no data)



Peril Legend

River Flood	Tsunami	Hailstorms	Volcano
Return Period [years]	Return Period	Hail days (>2cm) per 2500 km ² and year	Ash Thickness [cm]
50 year	500 years	Extreme (>1.0)	Extreme (>100 cm)
100 year	1000 years	Very High (0.8 - 1.0)	Very High (50 - 100)
200 year	2500 years	High (0.6 - 0.8)	Very High (40 - 60)
500 year	5000 years	Significant (0.4 - 0.6)	High (30 - 40 cm)
Pluvial Flood	10000 years	Moderate (0.2 - 0.4)	High (20 - 30 cm)
Return Period [years]	Windstorms	Low (0.1 - 0.2)	Significant (10 - 20 cm)
50 year	50 Year Peak Gust Range [m/s]	Very Low (<0.1)	Moderate (5 - 10 cm)
100 year	Extreme (> 70 m/s)	Tornado	Moderate (2 - 5 cm)
200 year	Very High (60-70 m/s)	F2-F5 Tornadoes/Year	Low (1 - 2 cm)
500 year	High (60-80 m/s)	Very High (0.75)	Low (0.1 - 1 cm)
Storm Surge	Medium (40-60 m/s)	High (0.6 - 0.75)	Lightning
Return Period [years]	Moderate (35-40 m/s)	Significant (0.35 - 0.5)	Annual flash rate per km ²
50 years	Moderate (30-35 m/s)	Moderate (0.2 - 0.35)	Extreme (>50)
100 years	Low (25-30 m/s)	Low (0.1 - 0.2)	Very High (35-50)
250 years	Low (20-25 m/s)	Very Low (0.1)	High (25-35)
500 years	Very Low (<20 m/s)	No Observation	High (21-28)
1000 years		Wildfires	High (16-20)
Seismic Hazard		Fire Hazard per 0.25° grid (1998-2016)	Significant (11-18)
Pseudo Spectral Acceleration [g]		Extreme (10)	Significant (7-10)
Extreme (1.82-20)		Very High (9)	Moderate (4-8)
Very High (1.22-1.82)		High (8)	Low (1-3)
Very High (0.82-1.22)		Significant (7)	Very Low (<1)
High (0.81-0.42)		Moderate (6)	
High (0.41-0.81)		Low (4)	
Significant (0.27-0.41)		Low (3)	
Moderate (0.18-0.27)		Very Low (2)	
Low (0.14-0.18)		Very Low (1)	
Low (0.09-0.14)			
Very Low (0.06-0.09)			

[Legal disclaimer](#)


©Swinburne All rights reserved

The information and opinions contained in the report are provided as at the date of the report and are subject to change without notice. Although the information used was taken from reliable sources, Swiss Re does not accept any responsibility for the accuracy or completeness of the details given. All liability for the accuracy and completeness thereof or for any damage or loss resulting from the use of the information contained in this report is expressly excluded. Under no circumstances shall Swiss Re or its Group companies be liable for any financial or consequential loss relating to this report.

NatCat Risk Assessment Report

Hazard Overview

Global intensity per peril according to Swiss Re scale 1 - 10 (0: no data)



Peril Legend

River Flood	Tsunami	Hailstorm	Volcano
Return Period [years]	Return Period	Hail days (>2cm) per 2600 km ² and year	Ash Thickness [cm]
50 year	500 years	Extreme (>1.0)	Extreme (>100 cm)
100 year	1000 years	Very High (0.8 - 1.0)	Very High (50 - 100 cm)
200 year	2500 years	High (0.6 - 0.8)	Very High (40 - 60 cm)
500 year	6000 years	Significant (0.4 - 0.6)	High (30 - 40 cm)
Pluvial Flood	10000 years	Moderate (0.2 - 0.4)	High (20 - 30 cm)
Return Period [years]	Windstorm	Low (0.1 - 0.2)	Significant (10 - 20 cm)
50 year	50 Year Peak Gust Range [m/s]	Very Low (<0.1)	Moderate (5 - 10 cm)
100 year	Extremely (70 m/s)		Modest (2 - 5 cm)
200 year	Very High (60-70 m/s)		Low (1 - 2 cm)
500 year	High (50-60 m/s)		Low (0.1 - 1 cm)
Storm Surge	Significant (40-60 m/s)		
Return Period [years]	Moderate (36-40 m/s)		
50 years	Moderate (30-36 m/s)		
100 years	Significant (30-36 m/s)		
250 years	Moderate (26-30 m/s)		
500 years	Low (20-26 m/s)		
1000 years	Low (20-26 m/s)		
Seismic Hazard	Very Low (>20 m/s)		
Pseudo Spectral Acceleration [g]	No Observation		
Extreme (1.82-20)			
Very High (1.22-1.82)			
Very High (0.82-1.22)			
High (0.81-0.82)			
High (0.41-0.61)			
Significant (0.27-0.41)			
Moderate (0.18-0.27)			
Low (0.14-0.18)			
Low (0.09-0.14)			
Very Low (0.08-0.09)			

Tsunami	Hailstorm	Volcano
Return Period	Hail days (>2cm) per 2600 km ² and year	Ash Thickness [cm]
500 years	Extreme (>1.0)	Extreme (>100 cm)
1000 years	Very High (0.8 - 1.0)	Very High (50 - 100 cm)
2000 years	High (0.6 - 0.8)	Very High (40 - 60 cm)
5000 years	Significant (0.4 - 0.6)	High (30 - 40 cm)
10000 years	Moderate (0.2 - 0.4)	High (20 - 30 cm)
50 years	Low (0.1 - 0.2)	Significant (10 - 20 cm)
100 years	Very Low (<0.1)	Moderate (5 - 10 cm)
200 years		Modest (2 - 5 cm)
500 years		Low (1 - 2 cm)
1000 years		Low (0.1 - 1 cm)
Pluvial Flood	Windstorm	Tornado
Return Period [years]	60 Year Peak Gust Range [m/s]	F2-F6 Tornadoes/Year
50 year	Extreme (>70 m/s)	Very High (>0.75)
100 year	Very High (60-70 m/s)	High (0.6 - 0.75)
200 year	High (50-60 m/s)	Significant (0.58 - 0.6)
500 year	Modest (36-40 m/s)	Moderate (0.2 - 0.36)
1000 years	Significant (30-36 m/s)	Modest (0.1 - 0.2)
Storm Surge	Low (26-30 m/s)	Very Low (<0.1)
Return Period [years]	Low (20-26 m/s)	No Observation
50 years	Low (20-26 m/s)	
100 years	Very Low (<20 m/s)	
250 years	Very Low (<20 m/s)	
500 years	No Observation	
1000 years		
Seismic Hazard	Wildfire	Lightning
Pseudo Spectral Acceleration [g]	Fire Hazard per 0.25° grid (1995-2016)	Annual flash rate per km ²
Extreme (1.82-20)	Extreme (10)	Extreme (>60)
Very High (1.22-1.82)	Very High (9)	High (0.6 - 0.75)
Very High (0.82-1.22)	High (8)	Significant (0.58 - 0.6)
High (0.81-0.82)	Significant (7)	Moderate (0.2 - 0.36)
High (0.41-0.61)	Moderate (6)	Modest (0.1 - 0.2)
Significant (0.27-0.41)	Moderate (5)	Very Low (0.1 - 0.2)
Moderate (0.18-0.27)	Low (4)	No Observation
Low (0.14-0.18)	Low (3)	
Low (0.09-0.14)	Very Low (2)	
Very Low (0.08-0.09)	Very Low (1)	

Legal disclaimer

©Swiss Re. All rights reserved.


The information and opinions contained in the report are provided as at the date of the report and are subject to change without notice. Although the information used was taken from reliable sources, Swiss Re does not accept any responsibility for the accuracy or comprehensiveness of the details given. All liability for the accuracy and completeness thereof or for any damage or loss resulting from the use of the information contained in this report is expressly excluded. Under no circumstances shall Swiss Re or its Group companies be liable for any financial or consequential loss relating to this report.

Guadalajara plant

NatCat Risk Assessment Report

Hazard Overview

Global intensity per peril according to Swiss Re scale 1 - 10 (0: no data)



Peril Legend

River Flood	Tsunami	Hailstorm	Volcano
Return Period [years]	Return Period	Hail days (>2cm) per 2600 km ² and year	Ash Thickness [cm]
50 year	500 years	Extreme (>1.0)	Extreme (>100 cm)
100 year	1000 years	Very High (0.8 - 1.0)	Very High (50 - 100 cm)
200 year	2500 years	High (0.6 - 0.8)	Very High (40 - 60 cm)
500 year	5000 years	Significant (0.4 - 0.6)	High (30 - 40 cm)
1000 years	10000 years	Moderate (0.2 - 0.4)	High (20 - 30 cm)
Pluvial Flood	Windstorm	60 Year Peak Gust Range [m/s]	Tornado
Return Period [years]	60 Year Peak Gust Range [m/s]	Significant (0.4 - 0.6)	F2-F6 Tornadoes/Year
50 year	Extreme (>70 m/s)	Extreme (>0.75)	Very High (>0.75)
100 year	Very High (60-70 m/s)	High (0.6 - 0.75)	High (0.6 - 0.75)
200 year	High (50-60 m/s)	Significant (0.58 - 0.6)	Significant (0.58 - 0.6)
500 year	Modest (36-40 m/s)	Moderate (0.2 - 0.36)	Moderate (0.2 - 0.36)
1000 years	Significant (30-36 m/s)	Modest (0.1 - 0.2)	Modest (0.1 - 0.2)
Storm Surge	Low (26-30 m/s)	Very Low (<0.1)	Very Low (<0.1)
Return Period [years]	Low (20-26 m/s)	No Observation	No Observation
50 years	Low (20-26 m/s)		
100 years	Very Low (<20 m/s)		
250 years	Very Low (<20 m/s)		
500 years	No Observation		
1000 years			
Seismic Hazard	Wildfire	Lightning	Annual flash rate per km ²
Pseudo Spectral Acceleration [g]	Fire Hazard per 0.25° grid (1995-2016)	Extreme (>60)	Extreme (>60)
Extreme (1.82-20)	Extreme (10)	Very High (9)	Very High (9)
Very High (1.22-1.82)	Very High (9)	High (8)	High (8)
Very High (0.82-1.22)	High (8)	Significant (7)	Significant (7)
High (0.81-0.82)	Significant (7)	Moderate (6)	Moderate (6)
High (0.41-0.61)	Moderate (6)	Modest (5)	Modest (5)
Significant (0.27-0.41)	Modest (5)	Low (4)	Low (4)
Moderate (0.18-0.27)	Low (4)	Low (3)	Low (3)
Low (0.14-0.18)	Low (3)	Very Low (2)	Very Low (2)
Low (0.09-0.14)	Very Low (2)	Very Low (1)	Very Low (1)
Very Low (0.08-0.09)	Very Low (1)		

Legal disclaimer

©Swiss Re. All rights reserved.


The information and opinions contained in the report are provided as at the date of the report and are subject to change without notice. Although the information used was taken from reliable sources, Swiss Re does not accept any responsibility for the accuracy or comprehensiveness of the details given. All liability for the accuracy and completeness thereof or for any damage or loss resulting from the use of the information contained in this report is expressly excluded. Under no circumstances shall Swiss Re or its Group companies be liable for any financial or consequential loss relating to this report.

Pacífico plant


NatCat Risk Assessment Report

Hazard Overview

Global intensity per pixel according to Swiss Re scale 1 - 10 (D: no data)



Peril Legend



[Local distributor](#)

Digitized by srujanika@gmail.com


*Swiss Re. All rights reserved.
The information and opinions contained in the report are provided as at the date of the report and are subject to change without notice. Although the information used was taken from reliable sources, Swiss Re does not accept any responsibility for the accuracy or comprehensiveness of the details given. All liability for the accuracy and completeness thereof or for any damage or loss resulting from the use of the information contained in this report is expressly excluded. Under no circumstances shall Swiss Re or its Group companies be liable for any financial or consequential loss relating to this report.

Mérida plant


NatCat Risk Assessment Report

Hazard Overview

Global Intensity map and connection to Sector Results - 10 Page detail



Peril Legend



[Legal disclaimer](#)

©Swiss Re. All rights reserved.
The information and opinions contained in the report are provided as at the date of the report and are subject to change without notice. Although the information used was taken from reliable sources, Swiss Re does not accept any responsibility for the accuracy or comprehensiveness of the details given. All liability for the accuracy and completeness thereof or for any damage or loss resulting from the use of the information contained in this report is expressly excluded. Under no circumstances shall Swiss Re or its Group companies be liable for any financial or consequential loss.

Golfo plant

2. Qualitative assessments

A descriptive assessment was carried out to 7 plants (the seven plants that are not assessed quantitatively). This evaluation was carried out in order to get information about the risks evaluated for the previous 10 plants.

This assessment was carried out taking into account the historical events and the probability of occurrence derived from physical factors.

A summary table is presented in the following slides.

Qualitative risk assessments



1.0 °C Scenario											
Short term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Low	Moderate	Low	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Low	Low	Moderate	Moderate	Low	Moderate
Guatemala	Low	Moderate	Low	Moderate	Low	Moderate	Low	Low	Low	Moderate	Low
IPS Loma Hermosa	Low	Low	Moderate	Low	Low	Low	Low	Low	Low	Low	Low
IPS San Martín	Low	Low	Moderate	Low	Low	Low	Low	Low	Low	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Low	Low	Moderate
Pilarica (Olivos)	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Mid Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Low	Moderate	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Low	Low	Moderate	Moderate	Low	Moderate
Guatemala	Low	Moderate	Moderate	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low	Moderate
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Low	Low	Moderate
Pilarica (Olivos)	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Long Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	High	Moderate	Moderate	Low	Low	High	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Moderate	Moderate	Moderate	Low	Low	Moderate
Guatemala	Low	High	High	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Moderate	Moderate	Low	Low

Qualitative risk assessments



1.5 ° C Scenario											
Short term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	Moderate	Low	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Low	Moderate	Moderate	Moderate	Low	Moderate
Guatemala	Low	Moderate	Low	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Low
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Low	Low	Low	Low	Low	Low
IPS San Martín	Low	Moderate	Moderate	Low	Low	Low	Low	Low	Low	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Low	Low	Low
Mid Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	High	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Moderate	Moderate	Moderate	Low	Low	Moderate
Guatemala	Low	High	Moderate	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low	Moderate
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Low	Low	Moderate	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Moderate	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Long Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	High	Moderate	Moderate	Low	Low	High	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	High	Moderate	Moderate	High	Low	Moderate
Guatemala	Low	High	High	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Moderate	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low

Qualitative risk assessments



2.0 ° C Scenario											
Short term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	Moderate	Low	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Low	Moderate	Moderate	Moderate	Low	Moderate
Guatemala	Low	Moderate	Low	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Low
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Low	Low	Low	Low	Low	Low
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low	Low
Pilar	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Mid Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	High	Moderate	Moderate	Low	Low	Moderate	Low	Low	Low	Low
Tuxtla	Low	Low	Moderate	High	Low	Low	Moderate	Moderate	Moderate	Low	Moderate
Guatemala	Moderate	High	Moderate	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Low	Low	Low
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Low	Low	Low
Pilar	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	Moderate	Moderate	Low	Moderate	Low	Low
Long Term											
Production Plant	River Flood	Pluvial Flood	Storm	Seismic Hazard	Tsunami	Windstorm	Hailstorm	Tornado	Wildfire	Volcano	Lighting
Lerma	Moderate	High	High	Moderate	Low	Low	High	Low	Low	Low	Low
Tuxtla	Low	Low	High	High	Low	Moderate	Moderate	Moderate	High	Low	Moderate
Guatemala	Moderate	High	High	Moderate	Low	Moderate	Low	Low	Moderate	Moderate	Moderate
IPS Loma Hermosa	Low	Moderate	Moderate	Low	Low	Moderate	High	High	High	Low	Moderate
IPS San Martín	Low	Moderate	Moderate	Low	Low	Moderate	High	Moderate	High	Low	Moderate
Pilar	Moderate	High	Moderate	Low	Low	High	High	Moderate	High	Low	Moderate
Pilarica (Olivos)	Moderate	Moderate	Moderate	Low	Low	High	High	Moderate	High	Low	Low

3. Appendix: Physical Risk study



The pictures presented in the following slides show the whole quantitative study carried out in our plants which included:

- Geographical information
- Strengths, weaknesses
- Construction of infrastructure information
- Financial loss scenarios (with material damages and business interruptions)
- Operations description and risks detected
- Business interruptions
- Natural risk assessment (NatCat assessment)
- Production Layout

As an outcome a suitable insurance policy was contracted against the risks detected.

Geographical information



Property Marketing Report
Rotoplas SAB de CV
5 Febrero 2020

LOCKTON

Contenido

Página	
Introducción General	4
Resumen Ejecutivo	5
Resumen Encuentros de Negocio	7
Localización	8
Comunicación	9
Desarrollo	9
Promoción	9
Intercambio de Negocio	14
Exposición a Riesgos Naturales	16
Gobernabilidad	16
Anexos	17

Construction of infrastructure information



Rotoplas 2020
Renta Latam

INFORMACIÓN GENERAL

Información del cliente

Impresos	Rotoplas SAB de CV
Teléfono	Planta Latam
Dirección y teléfono	021 9111 72 72 Carretera a Tlalnepantla Km. 100, Col. Ejido Los Lotes, Tlalnepantla, EDOMEX
Línea de emergencia	21 000754 - 101 476754
Horarios de respuesta	07:00 hrs
Oficina de producción para venta	017 000
Punto de contacto para ventas	Méjico
Oficina	Cludad de Méjico
Representante para:	Karen Diaz
Representante para:	J. Pedro Teguia
Fecha de revisión más reciente	5 de Marzo 2020
Otros	N/A

Executive summary

Strengths, weaknesses

<p>RESUMEN EJECUTIVO</p> <p>Socitos México realizó una visita a la planta Rotoplas León el 09 febrero del 2020 al propósito de llevar a cabo una exploración del sitio para diagnóstico de las condiciones actuales y determinar un perfil de riesgo de Incendio y Riesgos naturales.</p> <p>Para catalogación del programa de riesgos se sugiere el siguiente código de clasificación:</p> <ul style="list-style-type: none"> ▪ MARCO Código 100001: Fabricación de piezas plásticas de plástico <p>Fortalezas</p> <ul style="list-style-type: none"> ▪ Gestión de Administración de Riesgos: El grupo tiene un Comité Corporativo Integrado por la dirección General, dirección de cadena de suministro, recursos, seguridad e higiene, producción y área de administración de riesgos quienes dan seguimiento a los programas establecidos por Cia. Asesoresat. ▪ Gestión de Mantenimiento: La producción es monitoreada y administrada a través de SAP mediante de mantenimiento e inventarios de reacciones, plazos críticos, trabajo en proceso y almacenamiento para cada planta. Tipo de mantenimiento mecánico y eléctrico, para controladores a pie de máquina. El personal está conformado por personal operaciones, estructura de máquinas, moldeos y electromecánicos (con tres niveles de especialidad). ▪ Política de no fumar con sanciones por incumplimiento. ▪ Tipos Constructivos: No combustibles ▪ Líquidos inflamables: Cantidades mínimas en proceso principalmente para sellado (no más de 1000L), utilización de garrafas llenadas 100%, y almacenamiento exterior con diques móviles. ▪ Sistemas eléctricos: En media tensión realizan pruebas tetragráficas en tablero y subestación. Ademá de análisis de gases disueltos anuales. Parámetros con cobertura total. <p>Riesgos que cumplen con normatividad mexicana, pero es deseable mejorar para dar cumplimiento a un estándar internacional o una buena práctica.</p> <ul style="list-style-type: none"> ▪ Trabajos en caliente: De acuerdo a HSM-027-0199. ▪ Gas Natural: Instalación acreditada por la Unidad Verificadora, deseable aplicar protocolos mantenimiento e inspección de tubería interior en linea con código ASME. 	<p>Rotoplas 2020 Visita 01</p> <p>Vulnerabilidades</p> <ul style="list-style-type: none"> ▪ Orden y limpieza: En área de pesado, zona exterior de servicios y aumentar la frecuencia de limpicio hacia otras áreas del edificio como techos y corredores exteriores. ▪ Sistemas Eléctricos: baja tensión: Algunas lámparas residuales HID en proceso de cambio, se requiere equipo eléctrico clasificado clase II División 1 principalmente en área de pesado, nivel inspección y extracción. ▪ Sistema Fijo de Protección Contra Incendio: no incluye radiaciones, es sub-estándar NFPA. <p>Otrosas Inversiones y mejoras relevantes para Incendio:</p> <ul style="list-style-type: none"> ▪ Un programa de cambio de luminaria HID (High Intensity Discharge) se está llevando a cabo, principalmente en áreas de proceso y almacenamiento de materia prima con un avance de proyecto 20%. <p>Otras fallas más importantes del sitio:</p> <ul style="list-style-type: none"> ▪ Separación por tipo de uso. ▪ Inventario de producto terminado de 10 días en paro. ▪ Sitio principal para Call Center, Cuentas por Pagar y Servicio al Cliente. <p>Mejoras realizadas desde la última visita:</p> <ul style="list-style-type: none"> ▪ Se sugiere realizar una revisión a detalle de los valores de RI (Intercapital de Negocios e Interdependencia, especialmente para Rotoplas). Analizando volúmenes de materia prima e inventarios. Actualización marzo 2020: La revisión se está llevando a cabo con el área de Administración de Riesgos.
--	---

Financial loss scenarios (with material damages and business interruptions)

RESUMEN ESCENARIO DE PÉRDIDA

Los valores de Daño Material (DM) e Interrupción de Negocio (IN) son los reportados por el cliente al momento de la visita, la estimación de pérdida máxima se realiza en función de la exposición máxima esperada de un evento de incendio y/o explosión evaluado en campo y de la identificación del número de áreas de fuego.

Resumen 1	Incendio en Nave Rotoplas (Supuesto)	Cantidad	IN y/o PES
El escenario de incendio se presenta en la nave de botes (incidental), bajo las condiciones más adversas consideradas en el PES, se espera una propagación al resto de la propiedad. Se estima que la pérdida asociada sea al nivel de roturas conexas y reportadas.	Daño Material al 100%		
La probabilidad de incendio (generalmente liviano) es superior al 100% para un período de 10 meses.			
Pérdida potencial incendio = \$	Pérdida potencial incendio = USD 5.40.204,588	Pérdida potencial de IN =	USD 0.02.714,485

IN/IN (Pérdida Mínima Posible) Es la menor pérdida monetaria de daños materiales más pérdida de beneficio, cuando la industria es mínimamente capaz de operar y para mantener su función normalizada de un incendio o daño en el factor principal, cuando los medios de protección contra incendios están fuera de servicio y el control de incendios depende únicamente de las acciones de los trabajadores. Basado en el 10% estimación de separaciones entre edificios y considerando un retraso en la actuación de brigadas y/o de las autoridades públicas de emergencia.

IN/IN (Pérdida Máxima Posible) Es la mayor pérdida monetaria de daños materiales más pérdida de beneficio, cuando la industria es mínimamente capaz de operar y para mantener su función normalizada de un incendio o daño en el factor principal, cuando los medios de protección contra incendios están fuera de servicio y el control de incendios depende únicamente de las acciones de los trabajadores. Basado en el 10% estimación de separaciones entre edificios y considerando un retraso en la actuación de brigadas y/o de las autoridades públicas de emergencia.

DM: Daños Materiales.
IN/IN: Interrupción de Negocio.

DESCRIPCIÓN DEL RIESGO

Vista área y localización
Superficie: 11.627 m²
Áreas de Fuego: 2



Aerofoto de Google Earth Pro 2021

Construcción
División de Fuego : 2 Áreas de Fuego

Combustibilidad del edificio:

- Construcción NO combustible.
- Muro: Combinación de lámina acero/pintura con bloques de concreto.
- Techo: Combinación Lámina de acero con lámina acrílica transparente

Operations description and risks detected

Ocupación

Se fabrican tanques de polietileno alta densidad para almacenamiento de agua y tubería hidráulica de polietileno alta densidad.

La planta cuenta con 2 naves de 15 metros de separación y 1 almacén de materia prima.

- Nave de Rotomoldaje con una superficie de 12,000 m², fabrica contenedores para almacenamiento de agua de 250 a 25,000 L de capacidad.
- Nave de Rotoplas con una superficie de 12,000 m². Fabrica tuberías y uniones hidráulicas e industriales.
- Almacén Accesorios con superficie de 40% dentro Nave Rotoplas.

Rotomoldado Tanque

Proceso que consiste en el calentamiento a través de quemadores de gas licuado hasta un punto de acuerdo establecido y que gira lentamente creando un molde que permanece en posición. El molde se hace girar para que la materia prima se adhiera a su interior. Rotomoldables cuenta con una capacidad instalada de 800 toneladas para producciones de 250 a 25,000 litros con 10 moldes de diferentes tamaños. 2 moldes rotomoldados para la producción de tanques.

Las operaciones son alimentadas por gas natural a una presión de entrada de 3 litros/m³ con debandido a 2 litros/m³ y 1 litro/m³ en máxima para 200 litros. La planta cuenta con 2000 m³ de almacenamiento de gas natural. Ademas de las maquinas dadas en planta para explotación de fibra de vidrio a 2500 litros. La capacidad de respuesta entre plantas es Rotomoldados Industriales y Químicas.

Serigrafía

Despues del enfriamiento de los tanques, para el manejo el logotipo se realiza el proceso de serigrafía por un operador a través de un quemador de forma abierta. Los litros de serigrafía se almacenan en cestaderas de 200 lit. Posterior a serigrafía se hace una prueba de polietileno práctico.

Rotoplas Inyección / Extrusión de tubería, conexión y válvulas

Proceso de fundición y alimentación de polímero, aplicando calor a través de resistencias eléctricas, para ser liquidado a presión específica, velocidad y temperatura en la extrusión.

Alambiques cuentan con un proceso quemador a gas para polietileno de alta densidad.

Máquinas

- 10 Inyecciones que producen hasta 6 tubos de plástico por hora (200 horas).
- 8 extrusoras con producción hasta 800 kilogramos. Maquinaria americana y alemana.
- Linea de ensamblaje con máquinas de México marca Aher, Hedio, E, extrusión, linea ligar, 1 Cilindro marca Hydral.

Almacen

Edificio de tipo de almacén.

- Almacén de Materia Prima. Cuenta con más de 9 metros de altura con 5 techos. También cuentan con espacios de 500 m² dentro de Rotomoldaje superior no mayor a 200 m².

- 2 almacenes secos en Rotoplas y un almacén de Construcción. Ofrecen ventilación y refrigeración dentro de la nave con 7,200 m² de superficie sin protección de techados.

Almacen Materiales Peligrosos

- El almacén de materiales peligrosos se encuentra en el exterior.
- Se almacenan materiales para construcción (fibra y yeso), pinturas para edificios y plásticos, adhesivos en tanques de 30 galones (115 litros) sobre otros tipos de contenedores.
- Cuentan con gallardos apropiados (10,000 kg) de uso interno.

Servicios

- Energía eléctrica: 2 transformadoras. Una transformadora de 4000 kVA con sistema de aviso y aviso de emergencia, generador, un programa de ferrocarriles ya medida.
- Agua: Tres tanques. Propiedad gestionado por Comisión de Administración de Aguas para el desarrollo urbano de la ciudad de Mérida con almacenamiento de 1000 m³.
- Agua: Suministrada a través de un pozo central del pueblo.
- Compresores de alta presión.
- Planta de agua para sistemas de tratamiento y desinfección.
- Generador de agua para incendios.

Protección

- Estacionamiento de motocicletas 110*10 m.
- Estacionamiento de vehículos 100*10 m (100 lugares).
- Se cuenta con un punto para el lavado que puede alcanzar 40,000 lit. se realizan conexiones cada 10 años.
- 2 tanques de agua de 25,000 L cada uno, exclusivo para fuentes.
- Alarma con motor de combustión interna marca John Deere y batería de baterías.
- Un plan de asistencias de equipos requeridos por HSE está siendo evaluado por el Comité de Administración de Riesgos y Seguridad.
- Sistemas de detección de humo en edificios, almacenes y fábricas y conectados a panel central, se activan automáticamente. No se incluye las alarmas de rotulación con humo visible.
- La planta tiene de bombas con tiempo de respuesta promedio de 75 minutos.
- Bombas portátiles HEDY y COCO.
- Todas el personal cuenta con dependencia en techo y placa de aluminio de 100x100 cm y 100x100 cm.
- Se realizan simulacros de incendios y manejo de emergencias. El 100% de empleados son brigadistas, hay disponibilidad en todos los turnos.
- Cuarenta equipos completos de básculas.
- Equipo de respuesta automática (SCBA) en proceso de adquisición.

Business interruptions

Interrupción de Negocio

I. Recursos del sitio	<p>1. Edificio y estructura</p> <p>No se cuentan edificios ni estructuras complejas que puedan dejar vulnerables a la operación</p> <p>2. Equipo productivo</p> <p>Los equipos productivos cuentan con un análisis de refacciones críticas identificadas en el almacén de refacciones/SAP.</p> <ul style="list-style-type: none"> ✓ Inyección/extrusión: Las máquinas de origen alemán tienen redundancia con planta Lema para accesorios y Argentina para tubo. ✓ Rotomoldeo: El inventario de moldes cuenta con disponibilidad a nivel grupal, éstos se intercambian entre plantas constantemente dependiendo de la demanda productiva <p>3. Servicios propios</p> <p>Servicios utilizados:</p> <ul style="list-style-type: none"> ✓ Gas natural, energía eléctrica, chillers y compresores. <p>En caso de interrupción de suministro de gas natural los quemadores de rotomoldeo están habilitados para gas LP. El proceso de rotomoldeo no requiere demanda de suministro eléctrico como en el caso de compuestos, inyección y extrusión en donde deberán rentar generadores de electricidad.</p> <p>4. inventario y trabajo en curso</p> <p>Inventario:</p> <ul style="list-style-type: none"> ✓ De Conducción (tubería 25 días de inventario entre 8 planta y un almacén. ✓ La mayor parte del inventario se podrá gestionar a través de los comercializadores de Rotoplas. El trabajo en curso promedio por planta es de 35 toneladas diarias que pueden ser consultadas en tiempo real en línea.
II. Resiliencia general del sitio	<p>5. Ayudas dentro de la compañía</p> <p>Rotomoldeo: Cuenta con plantas distribuidas en México y Latinoamérica donde se puede producir mismos ítems. Plantas únicas: compuestos (Monterrey)</p> <p>Otra: Tubo (León) con redundancia en Argentina</p> <p>6. Ayuda del mercado/Proveedores</p> <p>Estrategias de recuperación parcial para compuestos se pueden llevar a cabo derivando con proveedores externos. Actualmente menos de un 15% de la producción se envía a externos para mantener la buena relación y el expertise de producción</p>

Rotoplas 2020
Planta León

III. Influencias externas	7. Interdependencia del grupo	Interdependencia materia prima, resina. Monterrey. Como el proceso de resina es un mezclado y no una fabricación del insumo. La estrategia de recuperación se basa en mover producto virgen a terceros en donde cada uno realizará una mezcla específica, una porción de la mezcla.
	8. Interrupción de Negocio Contingente	Interrupción de Negocio Contingente es NULA

Rotoplas 2020
Planta León

IV. Administración de la resiliencia del negocio	9. Gestión de continuidad de negocio	No existe un plan formalmente documentado. Varias acciones llevadas a cabo como operación normal de planta rotomoldeo y compuestos ayudan a practicar con regularidad recuperaciones alternas. Se considera un nivel de madurez medio sin opción de reducir 12 meses de Interrupción de Negocio
--	--------------------------------------	---

Natural risk assessment (NatCat assessment)

ANEXOS

**CumNet®
NetCat Risk Assessment Report**

Location Name: Puebla City
Location ID: 31100000000000000000
Latitude/Longitude: 19°15'50.000" N 98°25'50.000" W
Date: 2023-09-26 10:00:00
Comments:

NetCat Risk Assessment Report

Hazard Overview:

Risk Matrix: Cumulative Risk by Hazard Type (1 = High Risk)

Hazard Type	High Risk	Medium Risk	Low Risk
Earthquake	Very High	Medium	Low
Flood	Medium	Medium	Low
Tsunami	Low	Low	Low
Hurricane	Low	Low	Low
Volcano	Low	Low	Low
Wildfire	Low	Low	Low
Windstorm	Low	Low	Low
Tornado	Low	Low	Low
Lightning	Low	Low	Low

NetCat Risk Assessment Report

Hazard Overview:

Risk Matrix: Cumulative Risk by Hazard Type (1 = High Risk)

Hazard Type	High Risk	Medium Risk	Low Risk
Earthquake	Very High	Medium	Low
Flood	Medium	Medium	Low
Tsunami	Low	Low	Low
Hurricane	Low	Low	Low
Volcano	Low	Low	Low
Wildfire	Low	Low	Low
Windstorm	Low	Low	Low
Tornado	Low	Low	Low
Lightning	Low	Low	Low

**Exposición / Resumen Riesgos naturales
NetCat Risk Assessment Report**

Hazard Overview:

Risk Matrix: Cumulative Risk by Hazard Type (1 = High Risk)

Hazard Type	High Risk	Medium Risk	Low Risk
Earthquake	Very High	Medium	Low
Flood	Medium	Medium	Low
Tsunami	Low	Low	Low
Hurricane	Low	Low	Low
Volcano	Low	Low	Low
Wildfire	Low	Low	Low
Windstorm	Low	Low	Low
Tornado	Low	Low	Low
Lightning	Low	Low	Low

Colindantes

- [Mérida, Yuc. México](#)
- [San Felipe](#)
- [Ecatepec, Estado de México](#)
- [Cerro Tejajal Agua \(Tierra de lluvias para techado\)](#)

Production Layout

